QWISE-FM-SBJSGC-2019-SCS Company Standard

Hunan WISE New Material Technology Co., Ltd.

Powder sub-factory Powder product production process equipment safety technical regulations

Three-layer reciprocating screen safety technical regulations

Approved by: Zhaohui LIU Prepared by: Liyun Yun Xing Wang
Checked by Technical Dept: Yizhong Zhang and Yongshen Gong
Checked by Sub-Factory: Zhengchen Xu and Zhengdao Xiao
August 1, 2019 Release August 1, 2019 Effective

Hunan WISE New Material Technology Co., Ltd. Release

QWISE-FM-SBJSGC-2019-SCS Company Standard

Hunan WISE New Material Technology Co., Ltd.

Powder sub-factory

production process equipment safety technical regulations Three-layer reciprocating screen safety technical regulations

- 1. Wear the overalls and wear dust masks and ear protectors before operating.
- 2. Before starting the machine, the shuttle screen should be thoroughly inspected and confirmed to be normal before operation.
- 3. Each layer of screen is selected to be compatible with the particle size of the material being produced.
- 4. When sifting the sieve, pay attention to the screen frame and the screen frame to prevent the screen frame from being stuck, and then put the bolt on the bolt.
- 5. Start the round-trip sieve. After the equipment is running normally, the material can be cut and sieved. When the material is cut, the material should be evenly distributed on the screen.
- 6. It must be shut down when cleaning, checking, and handling equipment failures.
- 7. When the equipment is running, it should be stopped immediately and found to be abnormal. If necessary, notify the maintenance personnel.
- 8. It is forbidden to replace the screen frame while the equipment is running.

Approved by: Zhaohui LIU Prepared by: Liyun Yun Xing Wang
Checked by Technical Dept: Yizhong Zhang and Yongshen Gong
Checked by Sub-Factory: Zhengchen Xu and Zhengdao Xiao
August 1, 2019 Release August 1, 2019 Effective

Hunan WISE New Material Technology Co., Ltd. Release